

**J30. Ringhals 1: BWR****Sweden****Replacement of Primary Pipes Inside Containment**

**Description:** Replacement of above 100m of primary pipes inside the reactor containment and about 150m outside the containment due to intergranular stress corrosion cracking (IGSCC).

**Comments:** Internal outage report (in Swedish).

*For additional information contact: Krister Egner, Manager, Environment and Safety, Swedish State Power board, Ringhalsverket Nuclear Power Plant, S-43022 VaroBACKA, Sweden, Phone: 46 340-67150*