

J19. Ringhals 3: PWR**Sweden****Shot Peening of the Hot Leg Tubes of a Steam Generator****Description:** Shot peening of hot leg tubes**Comments:** Internal outage report (in Swedish) Olle Erixon, Shot Peening at Ringhals 3 and 4, 1986-1987, ALARA Considerations. Third European Scientific Seminar on Radiation Protection Optimization, "Advances in Practical Implementation," Madrid, Spain, September 12-14.*For additional information contact: Olle Erixon or Krister Egner, Vattenfall Ringhals NPP, S-43022 Varo-backa Sweden, Phone: 46-340-67150:*